

CERTIFICATE OF COMPLIANCE

Certificate Number E333135
Report Reference E333135-20181015
Issue Date 2020-FEBRUARY-25

Issued to: ELDOLED
1400 Lester Rd NW
Conyers GA 30012

**This certificate confirms that
representative samples of**

DRIVERS FOR LIGHT-EMITTING-DIODE ARRAYS,
MODULES AND CONTROLLERS
See Addendum

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety:

UL 8750, LED equipment for lighting products
CAN/CSA C22.2 No. 250.13-17, LED equipment for lighting
applications

Additional Information:

See the UL Online Certifications Directory at
<https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E333135
Report Reference E333135-20181015
Issue Date 2020-FEBRUARY-25

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

LED Driver, ECOdrive30B-M1Z0A, ECOdrive30B-M1Z0D, ECOdrive30B-M1M0Z , ECOdrive30S-M1Z0A, ECOdrive30S-M1Z0D, ECOdrive30S-M1M0Z , SOLOdrive30B-M1Z0A, SOLOdrive30B-M1Z0D, SOLOdrive30B-M1M0Z , SOLOdrive30S-M1Z0A, SOLOdrive30S-M1Z0D, SOLOdrive30S-M1M0Z , SOLOdrive30S-M2Z0A, SOLOdrive30B-M2Z0A, SOLOdrive30S-M2Z0D, SOLOdrive30B-M2Z0D, DUALdrive30S-M2Z0D, DUALdrive30B-M2Z0D, SOLOdrive30B-M1Z0X, SOLOdrive30S-M1Z0X, DUALdrive30S-M2Z0C, DUALdrive30B-M2Z0C



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

